


PLANT OF SURVEY

A parcel of land situated in the Southwest Quarter and in the Southeast Quarter of Section 3, Town 5 North, Range 2 East, Farmer Township, Defiance County, Ohio. Located within the North and the East of the First Principal Meridian of the Original Land Subdivisions of Ohio.



SURVEY LEGEND

- Placed 5/8" Rebar w/ Cap
 X Found PK Nail
 ○ Point Established this Survey
 — Found Iron Pin or Pipe
 M Found Monument Box
 X Found Railroad Spike
 X Placed MAG Nail

REFERENCE SURVEYS

- Volume 09-03-03
Volume 09-03-04
Volume 09-03-05
Volume 09-03-07
Volume 09-03-08
Volume 09-03-09

GENERAL OCCUPATION NOTE:

GENERAL NOTE:
No fences existed along the East, South or West boundaries of this property. All lines of occupation were either agricultural or lawn.

I hereby certify that I have surveyed the premises shown on the Plat above. All dimensions are shown in feet and decimals thereof. Since this survey does not include a title search, there could be easements or other encumbrances upon the land which are not shown on this survey plat. If these are required, please furnish the necessary information. The Bearings and Distances shown on the plat above are based on State Plane Coordinates, SP083, Zone-09 North. This survey has been recorded in the Defiance County Survey Records.



DATE: 10-27-2025	JOB: 25-158
------------------	-------------

**WIELAND SURVEYING
& ENGINEERING, LLC**
14067 County Road 20
West Unity, OH 43570
419-553-0112 - Voice

Brian M. Wieland - Ohio Registered Surveyor No. 8286

09-03-10